

CERTIFICATE OF COMPLIANCE

Certificate Number 20190111-E54612
Report Reference E54612-20190111
Issue Date 2019-JANUARY-11

Issued to: ROCKWELL AUTOMATION SWITZERLAND GMBH
INDUSTRIESTRASSE 20
5000 AARAU, SWITZERLAND

**This certificate confirms that
representative samples of**

Motor Controllers, Manual
See Addendum page for model list.

Have been investigated by UL in accordance with the
Standard(s) indicated on this Certificate.

Standard(s) for Safety:

UL 60947-1 LOW-VOLTAGE SWITCHGEAR AND
CONTROLGEAR - PART 1: GENERAL RULES
UL 60947-4-1 LOW-VOLTAGE SWITCHGEAR AND
CONTROLGEAR - PART 4-1: CONTACTORS AND
MOTOR-STARTERS - ELECTROMECHANICAL
CONTACTORS AND MOTOR-STARTERS
CSA C22.2 NO. 60947-4-1-14 LOW-VOLTAGE
SWITCHGEAR AND CONTROLGEAR -- PART 4-1:
CONTACTORS AND MOTOR-STARTERS --
ELECTROMECHANICAL CONTACTORS AND MOTOR-
STARTERS

Additional Information:

See the UL Online Certifications Directory at
<https://iq.ulprospector.com> for additional information.

This *Certificate of Compliance* does not provide authorization to apply the UL Mark. Only the UL Follow-Up Services Procedure provides authorization to apply the UL Mark.



Bruce Mahrenholz, Director North American Certification Program
UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>



CERTIFICATE OF COMPLIANCE

Certificate Number 20190111-E54612
Report Reference E54612-20190111
Issue Date 2019-JANUARY-11

Only those products bearing the UL Mark should be considered as being UL Certified and covered under UL's Follow-Up Services.

Look for the UL Certification Mark on the product.

This is to certify that representative samples of the product as specified on this certificate were tested according to the current UL requirements.

Bus bar assemblies, Models 140MP-A-W452, 140MP-A-W453, 140MP-A-W454, 140MP-A-W455, 140MP-A-W542, 140MP-A-W543, 140MP-A-W544, 140MP-A-W545, 140MP-A-W632, 140MP-A-W633, 140MP-A-W634, 140MP-A-W635, 140MP-A-HW453, 140MP-A-HW454, 140MP-A-HW455, 140MP-A-HW543, 140MP-A-HW544, 140MP-A-HW545, 140MP-A-HW633, KT5-32-DB-45-2, KT5-32-DB-45-3, KT5-32-DB-45-4, KT5-32-DB-45-5, KT5-32-DB-54-2, KT5-32-DB-54-3, KT5-32-DB-54-4, KT5-32-DB-54-5, KT5-32-DB-63-2, KT5-32-DB-63-3, KT5-32-DB-63-4, KT5-32-DB-63-5, KT5-32-DBH-45-3, KT5-32-DBH-45-4, KT5-32-DBH-45-5, KT5-32-DBH-54-3, KT5-32-DBH-54-4, KT5-32-DBH-54-5, KT5-32-DBH-63-3.

Bus bar assembly terminals, Models 140MP-A-WTN, 140MP-A-WTNH, KT5-32-A3N, KT5-32-A3NH.



Bruce Mahrenholz, Director North American Certification Program
UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>

