

CERTIFICATE OF COMPLIANCE

Certificate Number 20170830-E14840
Report Reference E14840-20140619
Issue Date 2017-AUGUST-30

Issued to: ROCKWELL AUTOMATION/ ALLEN-BRADLEY
1201 S 2nd St
Milwaukee, WI 53204-2410

This is to certify that representative samples of AUXILIARY DEVICES
Motor Controllers Auxiliary Devices, Models 193-EXP-AIO-31, CEP9-EXP-AIO-31.


Have been investigated by UL in accordance with the Standard(s) indicated on this Certificate.

Standard(s) for Safety: UL 60947-1 - Low-Voltage Switchgear and Controlgear - Part 1: General Rules
UL 60947-4-1 - Low-Voltage Switchgear and Controlgear - Part 4-1: Contactors and Motor-Starters - Electromechanical Contactors and Motor-Starters
CSA-C22.2 No. 60947-1 - Low-Voltage Switchgear and Controlgear - Part 1: General Rules
CSA-C22.2 No. 60947-4-1 - Low-Voltage Switchgear and Controlgear - Part 4-1: Contactors and Motor-Starters - Electromechanical Contactors and Motor-Starters

Additional Information: See the UL Online Certifications Directory at www.ul.com/database for additional information

Only those products bearing the UL Certification Mark should be considered as being covered by UL's Certification and Follow-Up Service.

Look for the UL Certification Mark on the product.



Bruce Mahrenholz, Director North American Certification Program
UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>

